

ITEM #10  
WRK S 02/09/10

Attachment F:  
Harlinsdale Photos



Front porch has settled and a lot of the trim has separated. This has allowed weather to cause dry rot of gutter boards, framing and soffits. This separation from settling has happened all the way around the home.







Deteriorated siding  
Recessed area of doorway is all rotted wood. Approx. a 3'x3' landing.



Most of the outside and inside damage was caused from the gutter system leakage over years







Entire wrap around porch is poorly supported.



Center of house- Caused by Widow's Peak leaking



01/23/2010 22:43